

Servicing Certificate

Customer Name - Door Servicing 2026

This is to certify that Tekta UK has carried out a full service and maintenance visit at the below site:

Customer Name: Example Customer

Site Name: Example Site

Job Number: 14490

This covered all of the products shown on the schedule set out below. This scheduled service and maintenance inspection from Tekta UK ensures continued compliance with Health and Safety under current legislation and contributes to the on-going safe operation of the products.

Technician: Names of Engineers
Completed Date: Monday 3rd August 2026

Signed on behalf of Tekta UK Ltd by:
Name, Account Manager



Sliding Coldroom Door					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
25	13975	Fridge 1	03/08/2026	GREEN - Good Working Order	
Speed Door (PVC)					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
26	14107	Loading Bay Side	03/08/2026	GREEN - Good Working Order	
Sliding Coldroom Door					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
27	14108	Fridge 3	03/08/2026	AMBER – Requires improvement	Damage to leading edge of door seal, 2x 2.1M lengths required
Speed Door (PVC)					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
28	14109	D18	03/08/2026	GREEN - Good Working Order	
Sliding Coldroom Door					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
29	14110	Detained Fridge	03/08/2026	AMBER – Requires improvement	Damage to leading edge of door seal requires replacement. Doors will have to be removed to replace seal.
Sliding Coldroom Door					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
31	14112	Despatch Fridge 3	03/08/2026	GREEN - Good Working Order	
Sectional Overhead Door					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
32	14113	Warehouse Tent 1	03/08/2026	GREEN - Good Working Order	

Sectional Overhead Door					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
33	14114	Warehouse Tent 2	03/08/2026	GREEN - Good Working Order	
Fire Shutter					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
34	14115	Loading Bays	03/08/2026	GREEN - Good Working Order	
Sliding Coldroom Door					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
35	14116	Dispatch Fridge 2	03/08/2026	AMBER – Requires improvement	Door seal and retainer damaged, new 3M retainer and 20M of 3000s gasket required. Bottom seal coming away, new seal and retainer required.
Sectional Overhead Door					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
38	14119	Bay 4	03/08/2026	RED - Safety Critical	Springs rusted and corroded; RH spring is snaking. Stretched and will require replacing. Will require use of a scissor lift, area is too busy to use during operating hours, will need to be done out of hours. Damage to bottom 2 panels, will require replacements. Panel size – 2445 x 610mm.

Sectional Overhead Door					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
39	14120	Bay 15	03/08/2026	AMBER – Requires improvement	Require new pair of spring buffers. Cover missing on motor. 2 rollers and brackets damaged/missing. Cables require adjusting as not running level. Bottom 2 panels are damaged and would recommend replacing.
Sliding Coldroom Door					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
40	14121	Bay 4 Fridge	03/08/2026	AMBER – Requires improvement	Handle is damaged, 3000s external handle replacement required.
Speed Door (PVC)					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
41	14122	29 Internal	03/08/2026	RED - Safety Critical	Door is isolated and not in use, heavy damage to guides and cables are hanging loose. Straps worn and bars are bent. Would require replacement guides, curtain, bars and straps. Replacement door recommended, as more cost effective than replacing all parts.

Fire Shutter					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
42	14123	Stores	03/08/2026	RED - Safety Critical	Failed door due to no safety brake, chain driven motor with sprocket. Non-compliant as fire shutter as not linked to fire alarm.
Dock Leveller					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
43	14124	Dispatch Bay 1	03/08/2026	RED - Safety Critical	Concrete around leveller isn't secure. Can shake with a hand. Catching on buffers when lip comes out. Warped ribs underneath platform. Frame moves when leveller is activated.
Sectional Overhead Door					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
44	14125	Despatch Bay 1	03/08/2026	GREEN - Good Working Order	
Dock Shelter					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
45	14126	Despatch Bay 1	03/08/2026	GREEN - Good Working Order	
Dock Leveller					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
46	14127	Dispatch Bay 2	03/08/2026	GREEN - Good Working Order	

Sectional Overhead Door					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
47	14128	Dispatch Bay 2	03/08/2026	GREEN - Good Working Order	
Dock Shelter					
Asset Number	Asset ID	Location	Asset Test Date	Compliance	Test Notes
48	14129	Dispatch Bay 2	03/08/2026	GREEN - Good Working Order	